

**Public Record – Summary Information on Underground Storage Tanks (USTs)  
Arizona Department of Environmental Quality (ADEQ)**

**Report Period: October 1, 2014 – September 30, 2015**

**General Information:**

Total Number of UST Facilities: 2,339  
Total Number of Open USTs: 6,538

**Summary Information for On-Site UST Inspections:**

Number of UST Facilities Inspected: 575  
Percent Significant Compliance<sup>1</sup>: 84%

**Summary Information for Leaking UST (LUST) Releases<sup>2</sup>:**

Number of Confirmed LUST Releases: 68 (at 44 facilities)

**Summary Information for Release Sources and Causes:**

Source			Cause													
			Spill		Overfill		Phys/Mech Damage		Corrosion		Install Problems		Other		Unknown	
	#	%	#	%	#	%	#	%	#	%	#	%	#	%	#	%
Tank	42	61			1	2	4	10							37	88
Piping	13	19					1	8							12	92
Dispenser	12	18					1	8							11	92
Submersible Turbine Pump																
Delivery Problem	1	2			1	100										
Other																
Totals	68	100		xxxx	2	xxxx	6	xxxx		xxxx		xxxx		xxxx	60	xxxx

<sup>1</sup> Percent compliance measures significant compliance with Arizona's UST regulatory requirements based on an on-site compliance inspection. Significant or major violations, such as non-compliance with the presence or operational capability of release detection, corrosion protection, overfill or spill prevention equipment would result in issuance of a Notice of Violation.

<sup>2</sup> Release, source and cause information is based on data associated with the 68 LUST releases reported during this reporting period. All open LUST release case files, 707 to date, are tracked in the Azurite database and are managed by ADEQ case managers within the UST Corrective Action Section.

To obtain more information on UST inspection and compliance issues, please call (602) 771-4196. To obtain more information on LUST issues, please call (602) 771-4289.