IRA-10-100
<0.010

Roger Rd

IRA-11-70
NS

IRA-15
NS

IRA-17
<0.010

IRA-18
NS

IRA-21
<0.010

IRA-16
<0.010

IRA-12-70
<0.010

IRA-19
<0.010

IRA-22
0.012

IRA-20
NS

IRA-23
NS

IRA-27
0.016

IRA-28
NS

IRA-29
<0.010

IRA-30
<0.010

SJ-MW-01
NS

SJ-MW-02
83.2

SJ-MW-03
NS

Prince Rd

Romero Rd

INTERSTATE 10

N

0 260 520 1,040 Feet

Perched Monitor Well

Figure 10
Perched Groundwater Chromium Concentration Map
October 2010
Miracle Mile WQARF Site
Tucson, Arizona

ADEQ Arizona Department of Environmental Quality

URS



Perched Monitor Well

Abandoned

Property Boundary

NS: Was not sampled at this time

Figure 11
Perched Groundwater Chromium Concentration Map (mg/L)
December 2011
Miracle Mile WQARF Site
Tucson, Arizona

ADEQ Arizona Department of Environmental Quality

URS